



## **SERVICE BULLETIN**

**15-T3-30**

DATE: 21\08\2015

MODELS CONCERNED:

All MK4 B, C, F & T Series Tractors

MK4 B Series B60-4TRAC, B250-4TRAC / C Series C50, C60, C80 / F Series F60-4TRAC, F250-4TRAC / T Series T50, T60 & T80.

CONCERN:

A service sub loom section offered for repairs as an alternative to changing the entire loom.

---

### **The Sub Loom**

The service department offers a sub loom section made available for dealers wishing to repair the cutter clutch and light loom connector sections of a main loom for the above mentioned tractors. This sub loom section allows the installer to replace a section of a damaged loom without the need to replace the entire main loom. The sub loom order part number is 449883200.

**Diagram shows a full loom with replacement section highlighted**





Diagram of sub loom section



Diagram of sub loom alongside full loom





Cut and prepare a break point in the main loom for connecting the sub loom spade connectors




Diagram of sub loom section with connector specifications

