

Tractor upgrade time line and check list

April 2015 - Aug 2015

Faults	Solution	Bulletin number / Kit number	Section
Drive belt failed	New drive modification kit.	Kit number 50100079	2
Dash board faulty	New board has been released with less functions to improve reliability.	448809300	2
Sticky forward and reverse pedals	Remove and grease pedals	11-T8-25	2
Belts failed and broken the loom for the clutch and the lights	Sub loom has been made for a faster repair.	15-T3-30 / Part number 449883200	2
Bearing house excess noise	Only PTO bearing houses with a 4mm clutch stop bracket.	15-08-37	2
Accessory doesn't work	Accessory wires for the attachments i.e. Scarifier / Chipper	14-T3-27	2
Deck belt falls of in the lower position or the tension lever keeps	Shim kit and new tension sleeve.	15-T4-71	3
Cut issue on a 36" / 38" decks	Deck speed up kit	15-T4-73	3
Customer would like a mulching deck.	New 42" mulch kit.	15-T4-74/ Kit number 50100036	3
Old PGC fitting the new style units and the belt is too short.	Belt size was increased	15-09-14	4
Handbrake stiff	Remove handbrake link and grease	N/A	
Wear on RHS PGC arm	Replace and grease arms	327056200	
	New Drop Link kit	50100090	
PTO bearings have failed.	New Bearing house Assembly	408806300	